

Ametek Us Gauge

Garanti: 12 ay
Bu ürüne ait Türkiye içi kapı teslim fiyat ve teslim süresi içeren teklifimizi almak için **info@yursat.com.tr** e-posta adresine başvuru yapabilir ya da ayrıntılı bilgi için +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaşabilirsiniz.
Ametek Us Gauge Markası, tedarik süresi için lütfen bizimle iletişime geçiniz.

Firmamız Ametek Us Gauge Türkiye Distribütörü veya temsilcisi değildir. Firmamız sipariş durumunda, belirtilen ürünlerde sadece Orjinal ve yeni ürün teklifi sunmaktadır. Bu sitede gösterilen Özel marka adları ve ticari markalar ilgili sahiplerinin mülkiyetindedir, talep durumunda kaldırılmaktadır.



Ürün	Açıklama
Dctg0300ddc021	
1404-133589	6" Stem-Mount Test Gauge 2000 psi
1404-132587	6"Precision Test Gauge, 1K PSI 1/2"ANPT
Sstsb0100plsv250	Slim Submersible Level Trmrtr 100PSI 0.69" Diameter Sm Bores
831tc0015blsa	SS Pressure Connection VAC-15PSI, 12-30 VDC/4-20 mA DC
88c007a2	Pressure Sensor IS Expls proof 0-3000PSIG, 4-20 MaDC OUTPUT
Sdtsb0100rlsv250	Submersible Level Transducer 100 PSI 230.7 FT H2O
831tc0030blsa	SS Pressure Connection VAC-30PSI, 12-30 VDC/4-20 mA DC
831tg1000clsa	SS Pressure Connection 0-1000 PSIG, 8-14 VDC/1-5 VDC
Pst360d3600003q9	Pressure Sensors Switch Transducer 0-6000psi
1404-132583	6"Precision Test Gauge, 200PSI 1/2"ANPT

Pst360d3500003q9	Pressure Sensors Switch Transducer 0-5000psi
1403-132593-Cl	6"Precision Test Gauge, 200PSI 1/2"ANPT, Oxygen-cleaned
88f003a2cs	Pressure Sensor IS Expls proof 0-30PSIG, 4-20 MaDC OUTPUT
831ta0100blsa	SS Pressure Connection 0-100 PSIA, 12-30 VDC/4-20 mADC
575sb0100fls250	Submersible Level Transmitter 100PSI(230.7FT H2O), IS, EMI
1403-132594	6"Precision Test Gauge, 30PSI 1/2"ANPT
88c003a2	Pressure Sensor IS Expls proof 0-30PSIG, 4-20 MaDC OUTPUT
1403-132604	6"Precision Test Gauge, 2000PSI 1/2"ANPT
88c006a2	Pressure Sensor IS Expls proof 0-1000PSIG, 4-20 MaDC OUTPUT
1403-132601	6"Precision Test Gauge, 600PSI 1/2"ANPT
Sstsb0015plsv060	Slim Submersible Level Trmitr 15PSI 0.69" Diameter Sm Bores
88c004a2	Pressure Sensor IS Expls proof 0-100PSIG, 4-20 MaDC OUTPUT
831tg0300clsa	SS Pressure Connection 0-0300 PSIG, 8-14 VDC/1-5 VDC
Sdtsb0030nlsv090	Submersible Level Transducer 30 PSI 69.2 FT H2O
575sb0060fls160	Submersible Level Transmitter 60PSI(138.4 FT H2O), IS, EMI
Sstsb0030plsv090	Slim Submersible Level Trmitr 30PSI 0.69" Diameter Sm Bores
1929-133792	4.5"Process Gauge, 5PSI 1/4"ANPT, Bottom
Pst360d3300003q9	Pressure Sensors Switch Transducer 0-3000psi
575sb0015nls060	Submersible Level Transmitter 15PSI, 34.6 FT H2O CSA, I.S Aprvd
88f002a2cs	Pressure Sensor IS Expls proof 0-15PSIG, 4-20 MaDC OUTPUT
Pst360d3010003q9	Pressure Sensors Switch Transducer 0-100psi
575sb0015els060	Submersible Level Transmitter 15PSI(34.6 FT H2O), IS, EMI
575sb0006els040	Submersible Level Transmitter 6 PSI(13.8FT H2O) EMI, I.S
831ta0015blsa	SS Pressure Connection 0-15 PSIA, 12-30 VDC/4-20 mA DC
149015	3.5"Digital Thermometer, Type K, -50 to 450F, Field Mnt., DC Power
Pst360d3002503q9	Pressure Sensors Switch Transducer 0-25psi
173484	Digital Thermometer Explosion Proof
831tg0030clsa	SS Pressure Connection 0-30 PSIG, 8-14 VDC/1-5 VDC

675pb0060wls160	Submersible Level Transmitter 60PSI(138.4 FT H2O), EMI, IS, CSA
1404-132582	6"Precision Test Gauge, 160PSI 1/2"ANPT
575sb0100rls250	Submersible Level Transmitter 100PSI(230.7FT H2O), EMI, I.S
Dr71004603300300	GAUGE
831tg0100clsa	SS Pressure Connection 0-100 PSIG, 8-14 VDC/1-5 VDC
Pst360d3200003q9	Pressure Sensors Switch Transducer 0-2000psi
149022	3.5"Digital Thermometer, Type K, -50 to 250C, Pnl.Mnt., Batt.Power
1403-132602	6"Precision Test Gauge, 1000PSI 1/2"ANPT
675pb0060mls160	Submersible Level Transmitter 60PSI(138.4 FT H2O), CSA, IS
831ta0030blsa	SS Pressure Connection 0-30 PSIA, 12-30 VDC/4-20 mA DC
88c001a2	Pressure Sensor IS Expls proof 3-15PSIG, 4-20 MaDC OUTPUT
1403-132597	6"Precision Test Gauge, 160PSI 1/2"ANPT
88f005a2cs	Pressure Sensor IS Expls proof 0-300PSIG, 4-20 MaDC OUTPUT
88c005a2	Pressure Sensor IS Expls proof 0-300PSIG, 4-20 MaDC OUTPUT
1403-132598	6"Precision Test Gauge, 200PSI 1/2"ANPT
88c002a2	Pressure Sensor, IS, Expls.Proof 0-15PSIG, 4-20MaDC Output
575sb0030nls090	Submersible Level Transmitter 30PSI, 69.2 FT H2O CSA, I.S Aprvd
149031	3.5"Digital Thermometer, Type K, 400-1500F, Field Mnt., Batt.Power
1403-132605	6"Precision Test Gauge, 3000PSI 1/2"ANPT
1403-132599	6"Precision Test Gauge, 300PSI 1/2"ANPT
88f004a2cs	Pressure Sensor IS Expls proof 0-100PSIG, 4-20 MaDC OUTPUT
675pb0006mls040	Submersible Level Transmitter 6 PSI(13.8FT H2O), CSA, IS
675pb0015wls060	Submersible Level Transmitter 15PSI(34.6 FT H2O), EMI, IS, CSA
1404-132580	6"Precision Test Gauge, 60PSI 1/2"ANPT
575sb0030els090	Submersible Level Transmitter 30PSI(69.2 FT H2O), IS, EMI
1403-133596	6" Precision Test Gauge 100 psi

1404-132591	6"Precision Test Gauge, 5K PSI 1/2"ANPT
675pb0030mls090	Submersible Level Transmitter 30PSI(69.2 FT H2O), CSA, IS
831tv0015blsa	SS Pressure Connection 0-30"HG VAC, 12-30 VDC/4-20mA DC
Pst360d3001503q9	Pressure Sensor Switch Transducer 0-15psi
831tc0060blsa	SS Pressure Connection VAC-60PSI, 12-30 VDC/4-20 mA DC
675pb0030wls090	Submersible Level Transmitter 30PSI(69.2 FT H2O), EMI, IS, CSA
1404-132578	6"Precision Test Gauge, 15PSI 1/2"ANPT
Pst360d3010k03q9	Pressure Sensors Switch Transducer 0-10, 000psi
149021	Digital Thermometer, -50 to 250C Battery Power, Field Mount, TypeK
Sdtsb0060rlsv160	Submersible Level Transducer 60 PSI 138.4 FT H2O
1404-132586	6"Precision Test Gauge, 600PSI 1/2"ANPT
831tg3000clsa	SS Pressure Connection 0-3000 PSIG, 8-14 VDC/1-5 VDC
575sb0006nls040	Submersible Level Transmitter 6 PSI, 13.8FT H2O CSA, I.S Aprvd
Pst360d3050003q9	Pressure Sensors Switch Transducer 0-500psi
1403-132595	6"Precision Test Gauge, 60PSI 1/2"ANPT
1403-133594	6"Prec.TestGauge, 30PSI, 1/4"ANPT FF/Pnl.Mnt
675pb0006wls040	Submersible Level Transmitter 6 PSI(13.8FT H2O), EMI, IS, CSA
Sptg 5000 E	
Sstsb0060plsv160	Slim Submersible Level Trmitter 60PSI 0.69" Diameter Sm Bores
1403-132606	6"Precision Test Gauge, 5000PSI 1/2"ANPT
1403-132596	6"Precision Test Gauge, 100PSI 1/2"ANPT
Pst360d3100003q9	Pressure Sensors Switch Transducer 0-1000psi
Pst360d3075003q9	Pressure Sensors Switch Transducer 0-750psi
88c008a2	Pressure Sensor IS Expls proof 0-5000PSIG, 4-20 MaDC OUTPUT
Pst360d3025003q9	Pressure Sensors Switch Transducer 0-250psi
Pst360d3005003q9	Pressure Sensors Switch Transducer 0-50psi
575sb0060rls160	Submersible Level Transmitter 60PSI, 138.4 FT H2O EMI, I.S
831tg5000clsa	SS Pressure Connection 0-5000 PSIG, 8-14 VDC/1-5 VDC

675pb0015mIs060	Submersible Level Transmitter 15PSI(34.6 FT H2O), CSA, IS
831tg0015clsa	SS Pressure Connection 0-15 PSIG, 8-14 VDC/1-5 VDC
1404-132586-Cl	6"Precision Test Gauge, 600PSI 1/2"ANPT, Oxygen-cleaned
1403-133598	6" Precision Test Gauge 200 psi
1403-132603	6"Precision Test Gauge, 1500PSI 1/2"NPT, LBM
Pst360d3400003q9	Pressure Sensors Switch Transducer 0-4000psi
1404-132589	6"Precision Test Gauge, 2K PSI 1/2"ANPT