

Noshok



Garanti: 12 ay

Bu rne ait Trkiye ii kapı teslim fiyat ve teslim sresi ieren teklifimizi almak iin info@yursat.com.tr e-posta adresine bařvuru yapabilir ya da ayrıntılı bilgi iin +90 224 240 03 04 numaralı telefonumuzdan bizlere ulařabilirsiniz. **Noshok** Markası, tedarik sresi iin ltfen bizimle iletiřime geiniz.

Firmamız Noshok Trkiye Distribtr veya temsilcisi deęildir. Firmamız sipariř durumunda, belirtilen rnlerde sadece Orjinal ve yeni rn teklifi sunmaktadır. Bu sitede gsterilen zel marka adları ve ticari markalar ilgili sahiplerinin mlkiyetindedir, talep durumunda kaldırılmaktadır.

rn	Aıklama
25-901-30-psi/kpa	
25-901-200-psi/kpa	
25-901-400-psi/kpa	
25-901-100-psi/kpa	
25-911-5000-psi/kpa-PMC	
25-911-3000-psi/kpa-PMC	
25-901-60-psi/kpa	
60-500-3000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-3000 psi/kPa
60-510-20000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-20000 psi/kPa
615-60a-2-1-2-3	Heavy Duty Pressure Transducer 60 PSIA
60-500-2000-Psi/Kpa	6"Pressure Gauge, 2000PSI 1/2"NPT, Lower
200-150-2-5-2-1	Pressure Transducer 0-150 PSIG
100-30vac-1-1-2-7	Current Output Pressure XMTR -30inHg-0 psig, 4-20mA, 2-wire
621-1000-1-1-8-6	Explosion-Proof Pressure Transmitter 1000 PSIG
40-510-30000-Psi/Kpa	4" Liquid Pressure Gauge 0 to 30000 psi/kPa
615-100-1-2-2-1-St8	Heavy Duty Pressure Transducer 100 PSIG
60-410-1000-Psi	6" Pressure Gauge 1000 psi
616-300-1-1-11-14	Heavy Duty Pressure Transducer 300 PSI
627-100-1-1-N-38-10	Submersible Pressure Transducer 100 psig
622-300-1-1-11-6	Explosion-Proof Pressure Transmitter 300 PSI

60-410-2000-Psi/Kpa	6" Pressure Gauge 0 to 2000 psi/kPa
200-30v-2-5-2-1	Pressure Transducer -30"Hg to 0 PSIG
100 100 1 1 2 7	
60-510-1500-Psi	6" Pressure Gauge Liquid Filled 0 psi-1500 psi
800-1-2-30-2-St8	RTD Temperature Transmitter
408-Mfs	1" NPTF Hard Seat SS Needle Valve
850-2-8-50/400-2-040-6	TEMPERATURE TRANSMITTER -50 400DEGF
100-30/150-1-1-2-7	Pressure Transmitter -30"Hg/150psig
60-510-300-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-300 psi/bar
60-410-1500-Psi/Bar	6"Press.Gauge, 0-1500PSI/bar, 0 to 1500 psi/bar
60-500-80000-Psi	6" Pressure Gauge Liquid Filled 0 psi-80000 psi
60-510-10000-Psi/Kpa	6" Pressure Gauge Liquid 10, 000psi/KPA
40-410-30000-Psi/Kpa	4" Pressure Gauge, 30000psi/kPa Dry, 1/2npt Back
615-15a-2-2-6-14	
800-1-2--14.5/75-2	RTD Temperature Transmitter
615-30/15-2-2-6-14	
60-410-5000-Psi	6" Pressure Gauge 5000 psi
60-510-1500-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-1500 psi/kg
622-15-1-1-8-6	Explosion-Proof Pressure Transmitter 15 PSIG
60-410-30"vac/Kg/Cm2	6" Pressure Gauge -30 inHg/kg/cm2 to 0
615-30v-1-1-2-8	Pressure Transmitter, -30VAC/0 1/4"NPTM, 4-20mA
100-200-2-1-2-6	Pressure Transmitter, 200PSIG 4-20mA 2-Wire, 1/4"NPTM, 36"Cable
St8	SS Threaded Orifice
200-150-2-5-2-7	Voltage Output Transducer 0-10VDC, 1/4"NPTM
615-150-1-1-8-8-St8	Heavy Duty Pressure Transducer 150 PSI
1000-30/60-2-1	Digital Pressure Gauge -30 inHg to 60
100-15a-2-1-2-1-St8	Pressure Transmitter, 0-15 PSIA
615-2000-2-2-6-14	
615-72000-1-2-6-14	
	3.3"Press.Gauge, -30"Hg to145PSI 1/4"NPTM, Peak Memory,

1000-30/145-2-1-Rcp	Boot
60-510-3000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-3000 psi/kPa
628-5000-1-1-H-14-3-Ch	628 Series IS Hammer Union Xmtr 5000psi, 0.25%FS, 4-20mA, Bendix
621-3000-1-1-8-6	Explosion-Proof Pressure Transmitter 3000 PSIG
625-15000-1-1-2-14-St8	Pressure Transmitter, 15, 000psi .25%A, 4-20mA, 1/2 Conduit,
60-410-30"vac	6" Pressure Gauge -30"Hg Vac-0 PSI
60-510-5000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-5000 psi/kPa
615-20000-2-2-6-14	
628-10000-1-1-H-14-36-Ch	628 Series IS Hammer Union Xmtr 10k psi, 0.25%FS, 4-20mA, Cable
612-25-1-1-N-50	Submersible Level Transducer 0-250 PSIG
60-410-3000-Psi/Kpa	6" Pressure Gauge 0 to 3000 psi/kPa
628-15000-1-1-H-14-3-Ch	628 Series IS Hammer Union Xmtr 15k psi, 0.25%FS, 4-20mA, Bendix
200-30-2-5-2-1	Pressure Transducer 0-30 PSIG
60-510-15-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-15 psi/bar
100-30v-1-1-2-1-St8	Pressure Transmitter -30 inHg to 15 psig
621-500-1-1-2-6	Explosion-Proof Pressure Transmitter 500 PSIG
615-2000-1-2-6-14	
60-410-20000-Psi	6" Pressure Gauge 20000 psi
60-510-30-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-30 psi/bar
800-2-2-300-2-Rb	RTD Temperature Transmitter
755-1500-1-1-8-24	Digital Pressure Transducer 1500 psi
406-Ffs	3/4" NPT F Hard Seat SS Needle Valve
612-5-1-1-N-4	Submersible Level Transducer 0-5 PSIG
60-510-600-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-600 psi/kPa
60-510-1000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-1000 psi/kPa
100-100a-1-1-2-7	Pressure Transducer, 100 PSIA 4-20mA 2-Wire, 1/4"NPTM
102 Mfs 1 4 Npt Male	
615-10000-1-5-2-8	Heavy Duty Pressure Transducer 10000 PSIG

100-3000-1-1-2-6	Pressure Transmitter 0-3000 PSIG
60-510-6000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-6000 psi/kg
100-15-1-1-2-6-St8	Pressure Transmitter 0-15psiG 4-20mA Output, .5%FS, 1/4npt Male
615-30000-2-1-6-36	Pressure Transducer, 30, 000psi .125%a, 4-20mA, 36"Cbl.9/16-18
615-20000-1-2-6-14	
612-5-1-1-N-50	Submersible Level Transducer 5 PSIG
60-510-2000-Psi	6" Pressure Gauge Liquid Filled 0 psi-2000 psi
615-58000-1-2-6-14	
60-400-20000-Psi/Bar	6" Pressure Gauge, 20K PSI/bar
60-410-10000-Psi	6" Pressure Gauge 10000 psi
200-15a-2-5-2-1	Pressure Transducer, 0-15 PSIA
60-500-6000-Psi	6" Pressure Gauge Liquid Filled 0 psi-6000 psi
615-72000-1-1-8-8	Heavy Duty Pressure Transducer 72000 PSIG
100-30vac-2-1-2-7	Pressure Transmitter -30"Hg to 0 PISG
612-30-1-1-N-50	Submersible Level Transducer 0-30 PSIG
60-510-60-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-60 psi/kPa
60-410-15000-Psi/Bar	6"Press.Gauge, 0-15K PSI/bar, 0 to 15000 psi/bar
60-400-10000-Psi	6" Pressure Gauge, 10000 PSI
60-410-15000-Psi/Kpa	6" Pressure Gauge 0 to 15000 psi/kPa
60-510-160-Psi	6" Pressure Gauge Liquid Filled 0 psi-160 psi
1000-600-2-1-Rcp	Digital Pressure Gauge, 600PSIG 1/4"NPTM, Peak Memory, Protector
621-1000-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 1000 PSIG
100 300 1 1 2 7	
60-510-300-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-300 psi/kg/
100-5000-2-1-1-7	Pressure Transmitter 0-5000 PSIG
615-10000-2-5-2-8	Heavy Duty Pressure Transducer 10000 PSIG
60-500-1500-Psi	6" Pressure Gauge Liquid Filled 0 psi-1500 psi
621-10000-1-1-2-6-St8	Explosion-Proof Pressure Transmitter 10000 PSIG
615-500-2-2-6-14	

800-1-2-3750-2	RTD Temperature Transmitter
800-1-2-14.5/30-2	RTD Temperature Transmitter
60-410-10000-Psi/Bar	6"Press.Gauge, 0-10K PSI/bar, 0 to 10000 psi/bar
412-Mfs	1-1/2" NPTF Hard Seat SS Needle Valve
615-15a-1-2-6-14	
60-510-600psi-Ssff	6" Pressure Gauge, 0-600 PSI
628-10000-1-1-H-14-3-Ch	628 Series IS Hammer Union Xmtr 10k psi, 0.25%FS, 4-20mA, Bendix
60-510-600-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-600 psi/kg/
60-500-10000-Psi	6" Pressure Gauge Liquid Filled 0 psi-10000 psi
60-400-40000-Psi	6" Pressure Gauge, 40000 PSI
628-5000-1-1-H-14-44-Ch	628 Series IS Hammer Union Xmtr 5k psi, 0.25%FS, 4-20mA, Glenair
615-36000-2-2-6-14	
615-3000-2-1-2-1	Heavy Duty Pressure Transducer 3000 PSIG
40-400-40000-Psi	4" Pressure Gauge 0 to 40000 psi
612-10-1-1-W-20	Submersible Level Transducer 0-10 PSIG
100-10-1-1-2-6	Pressure Transmitter, 0-10 PSIG
60-410-6000-Psi	6" Pressure Gauge 6000 psi/bar
615-30/100-2-2-6-14	
615-1000-1-2-6-14	
200-5000-2-2-2-7	Pressure Transducer 5000 PSIG
60-510-10000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-10000 psi/bar
60-510-600-Psi	6" Pressure Gauge Liquid Filled 0 psi-600 psi
60-510-1000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-1000 psi/kg
800-1-2-300-2	RTD Temperature Transmitter
100-60-1-1-2-6	Pressure Transmitter 0-60 PSIG
625-2-1-1-8-8	Intrinsically Safe Pressure Transmitter 2 PSIG
100-100-1-1-2-6	Pressure Transmitter, 100PSIG 4mA-20mA 2-Wire, 1/4"NPTM, 36"Cbl
615-750-2-2-6-14	
5530-Mms	5 Valve Manifold

60-500-2000-Psi-Rf	6" Pressure Gauge 2000 PSI
60-510-1500-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-1500 psi/kPa
615-145000-2-2-6-14	
621-5000-1-3-2-6	Explosion-Proof Pressure Transmitter 5000 PSIG
100 5000 1 1 3 7	
60-400-15000-Psi/Kg/Cm2	6" Pressure Gauge, 15KPSI/kg/cm2
621-2000-1-1-2-6	Explosion-Proof Pressure Transmitter 2000 PSIG
615-30000-2-2-6-14	
615-7500-2-2-6-14	
60-400-15000-Psi/Bar	6" Pressure Gauge, 15K PSI/bar
60-500-1000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-1000 psi/kPa
60-510-3000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-3000 psi/bar
60-410-15000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 15000 psi/kg/cm2
615-100-1-1-2-6	Heavy Duty Pressure Transducer 100 PSIG
800-1-2-6000-2	RTD Temperature Transmitter
60-500-3000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-3000 psi/bar
615-3000-1-2-6-14	
60-410-1500-Psi/Kg/Cm2	6" Pressure Gauge 0 to 1500 psi/kg/cm2
60-500-6000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-6000 psi/bar
615-115000-1-2-6-14	
615-30/200-2-2-6-14	
615-30-1-2-2-1	Heavy Duty Pressure Transducer 30 PSI
60-400-30000-Psi	6" Pressure Gauge, 30000 PSI
60-410-15000-Psi	6" Pressure Gauge 15000 psi
60-510-15000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-15000 psi/kPa
60-510-15000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-15000 psi/k
800-2-2-1450-2	RTD Temperature Transmitter
800-1-2-1450-2	RTD Temperature Transmitter
60-510-300-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-300 psi/kPa
615-72000-2-2-6-14	

100-500-2-1-3-7	Pressure Transmitter, 0-150PSIG
615-30/150-2-2-6-14	
615-150a-1-2-6-14	
25-123459-1-Rcp	Rubber Boot for Back Mount (uninstalled)
60-510-20000-Psi	6" Pressure Gauge Liquid Filled 0 psi-20000 psi
615-4000-1-2-6-14	
60-510-1500-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-1500 psi/bar
615-30-2-2-6-14	
615-5000-2-1-2-1	Heavy Duty Pressure Transducer 5000 PSIG
60-410-1500-Psi	6" Pressure Gauge 1500 psi
60-510-60-Psi	6" Pressure Gauge Liquid Filled 0 psi-60 psi
60.500.20000	
615-87000-2-2-6-14	
800-1-2-30-2	RTD Temperature Transmitter
40-510-100psi/Bar-Cc	4" Pressure Gauge w/Certified Calibration, 100PSI/bar
621-2000-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 2000 PSIG
60-400-1000-Ssff	6" Pressure Gauge, 1000 PSI
60-410-3000-Psi/Bar	6"Press.Gauge, 3K PSI/bar, 1/2" 0 to 3000 psi/bar
1000-1450-2-1	Digital Pressure Gauge 0-1, 450 PSIG
800-3-2-2400-2	RTD Temperature Transmitter
615-3000-2-1-2-8	Heavy Duty Pressure Transducer 3000 PSIG
60-410-3000-Psi	6" Pressure Gauge 3000 psi
40-500-40000-Psi	4" Liquid Pressure Gauge 40000 psi
100-25-1-1-2-6	Pressure Transducer, 0-25PSI
60-510-15000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-15000 psi/bar
615-145000-1-2-6-14	
615-5000-1-1-8-8-St8	Heavy Duty Pressure Transducer 5000 PSIG
60-510-100-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-100 psi/bar
615-60a-2-2-6-14	
616-100-1-1-11-1	Heavy Duty Pressure Transducer 100 PSIG

60-400-60000-Psi	6" Pressure Gauge, 60000 PSI
616-2-2-5-2-8	Heavy Duty Pressure Transducer 2 PSIG
800-1-2-2400-2	RTD Temperature Transmitter
1000-5000-2-1	Digital Gauge, 0-5000psiG Peak Memory, 1/4nptM
615-300-1-1-8-8-St8	Heavy Duty Pressure Transducer 300 PSIG
612-10-1-1-N-25	Submersible Level Transducer 10 PSIG
60-410-5000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 5000 psi/kg/cm2
615-600-2-2-6-14	
60-410-2000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 2000 psi/kg/cm2
60-400-80000-Psi	6" Pressure Gauge, 80000 PSI
60-410-6000-Psi/Kpa	6" Pressure Gauge 0 to 6000 psi/kPa
615-10000-1-2-6-14	
11-0-12-4-615-1-46-1-8	Sanitary Transmitter, 0-60PSIG
625-100-1-1-8-14	Intrinsically Safe Pressure Transmitter 100 PSIG
200-30/30-2-2-2-1	Pressure Transducer -30"Hg to 30PSIG
800-1-5-1450-2-Rb	RTD Temperature Transmitter 1/4" NPT Female Process Connect
60-400-10000-Psi/Kg/Cm2	6" Pressure Gauge, 10KPSI/kg/cm2
60-510-30" Vac	6" Pressure Gauge Liquid Filled -30 inHg-0
612-200in-2-1-W-12	Submersible Level Transducer 0-200" H2O
621-30/30-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 30"Hg to 30 PSIG
615-30000-1-2-6-14	
628-15000-1-1-H-14-36-Ch	628 Series IS Hammer Union Xmtr 15k psi, 0.25%FS, 4-20mA, Cable
615-15000-2-5-2-8	Heavy Duty Pressure Transducer 15000 PSIG
60-400-10000-Psi/Bar	6" Pressure Gauge, 10K PSI/bar
60-800-200-Psi	6" Precision Test Gauge, 200 PSI
60-510-100-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-100 psi/kg/
60-510-15-Psi	6" Pressure Gauge Liquid Filled 0 psi-15 psi
615-30/60-2-2-6-14	
60-510-30" Vac/Kg/Cm2	6" Pressure Gauge Liquid Filled -30 inHg/kg/cm2-0

60-510-10000-Psi	6" Pressure Gauge Liquid Filled 0 psi-10000 psi
100-30-2-1-2-6	Pressure Transmitter, 30 PSIG
60-410-20000-Psi/Bar	6"Press.Gauge, 0-20KPSI/bar, 1/2" 0 to 20000 psi/bar
615-15000-1-1-8-8-St8	Heavy Duty Pressure Transducer 15000 PSIG
1000-3000-2-1	Digital Pressure Gauge 0-3000 psig
615-6000-1-2-6-14	
615-3000-2-2-6-14	
615-100000-2-2-6-14	
615-7500-1-2-6-14	
615-15000-1-1-8-1	Heavy Duty Pressure Transducer 15000 PSIG
60-500-3000-Psi	6" Pressure Gauge Liquid Filled 0 psi-3000 psi
60-410-30"vac/Kpa	6" Pressure Gauge -30 inHg/kPa to 0
60-500-6000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 6000 psi/kg/cm2
615-30/30-2-2-6-14	
100-5000-2-1-2-2	Pressure Transmitter, 5000 PSI 1/4"NPTM, 4-20mA, 0.25%A
200-2000-2-2-2-1	Pressure Transducer 0-2000 PSIG
60-410-10000-Psi/Kpa	6" Pressure Gauge 0 to 10000 psi/kPa
60-510-160-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-160 psi/kg/
615-30vac-2-2-6-14	
615-15000-1-2-6-14	
60-410-20000-Psi/Kpa	6" Pressure Gauge 0 to 20000 psi/kPa
60-510-2000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-2000 psi/kPa
612-2-1-1-N-50	Submersible Level Transducer 0-2 PSIG
615-6000-1-1-8-8-St8	Heavy Duty Pressure Transducer 6000 PSIG
1000-2000-2-1	Digital Gauge 0-2000 psig
612-5-1-1-N-40	Submersible Level Transducer 5 PSIG
800-2-2-30-2-Rb	RTD Temperature Transmitter
621-600-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 600 PSIG
621-60-1-1-2-6	Explosion-Proof Pressure Transmitter 60 psig
60-410-2000-Psi/Bar	6"Press.Gauge, 0-2K PSI/bar, 1/2" 0 to 2000 psi/bar
11-0-12-4-615-1-58-1-1	Sanitary Pressure Transmitter 0-200 PSIG

100-100-1-1-2-6-St8	Pressure Transmitter, 100psiG 4-20mA Output, .5%FS, 1/4npt Male
60-510-5000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-5000 psi/kg
100-30v-2-1-2-7-St8	Pressure Transmitter -30 inHg to 0 psig
615-5000-1-5-2-1	Heavy Duty Pressure Transducer 5000 PSIG
100-5000-1-1-2-6-St8	Pressure Transmitter 0-5000 PSIG
615-6000-2-2-6-14	
615-30v-2-2-2-1-St8	Heavy Duty Pressure Transducer -30inHg to 0 PSI
625-100-2-1-8-14	Intrinsically Safe Pressure Transmitter 100 PSIG
60-510-100-Psi	6" Pressure Gauge Liquid Filled 0 psi-100 psi
60-510-5000-Psi	6" Pressure Gauge Liquid Filled 0 psi-5000 psi
621-15-1-1-8-6	Explosion-Proof Pressure Transmitter, 15PSIG
60-510-60-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-60 psi/bar
800-1-2-9000-2	RTD Temperature Transmitter
621-300-1-1-8-6	Pressure Transmitter, 300PSI 1/2"NPTM, 4-20mA
615-600-1-2-6-14	
60-500-15000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 15000 psi/kg/cm2
60-500-20000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-20000 psi/bar
800-1-2-750-2	RTD Temperature Transmitter
615-87000-1-2-6-14	
100-3000-2-1-3-7	Pressure Transmitter 3, 000 psiG .25%A, 4-20mA Output
60-400-20000-Psi	6" Pressure Gauge, 20000 PSI
60-410-5000-Psi/Kpa	6" Pressure Gauge 0 to 5000 psi/kPa
628-15000-1-1-H-14-44-Ch	628 Series IS Hammer Union Xmtr 15k psi, 0.25%FS, 4-20mA, Glenair
100-30/15-1-1-2-6	Pressure Transmitter, 1/8npt M -30"Hg to 15psig, 4-20mA
615-200-2-2-2-1	Pressure Transmitter, 200PSIG w/36"Cable, 1/4"NPTM, 0-5VDC
615-10-2-2-2-1-St8	Heavy Duty Pressure Transducer 10 PSIG
615-60-2-2-6-14	
612-100inh2o-1-1-N-50	Level Transmitter, 100" H2O .25%A, 4-20mA, 50' Cable
60-510-3000-Psi	6" Pressure Gauge Liquid Filled 0 psi-3000 psi

25-123459-0-Rcp	Rubber Boot for BTM Mount Gauge (installed)
100-600-2-1-2-6	Pressure Transmitter 0-600 psig 1/2npt Conduit.
1000-6000-2-1	Digital Gauge 0-6000 psig
60-510-6000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-6000 psi/bar
60-410-1500-Psi/Kpa	6" Pressure Gauge 0 to 1500 psi/kPa
200-30a-2-5-2-1	Pressure Transducer, 0-30 PSIA
60-510-30-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-30 psi/kPa
621-10000-1-3-8-6	Explosion-Proof Pressure Transmitter 10000 PSIG
60-500-100000-Psi	6" Pressure Gauge Liquid Filled 0 psi-100000 psi
615-5000-2-2-6-14	
615-30a-2-2-6-14	
615-30a-1-2-6-14	
615-500-1-2-6-14	
615-1500-1-2-6-14	
40-510-30000-Psi	4" Liquid Pressure Gauge 0 psi to 30000 psi
410-Ffs	1-1/4" NPTF Hard Seat SS Needle Valve
1000-7500-2-1	Digital Gauge 0-7500 psig
615-10000-1-1-8-8-St8	Heavy Duty Pressure Transducer 10000 PSIG
60-510-60-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-60 psi/kg/c
60-500-6000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-6000 psi/kPa
60-510-10000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-10000 psi/k
1000-10000-2-1	Digital Pressure Gauge, 10K PSI 1/4"NPTM, Peak Memory
60-510-200-Psi	6" Pressure Gauge Liquid Filled 0 psi-200 psi
615-15000-2-1-8-1	Heavy Duty Pressure Transducer 15000 PSIG
60-510-20000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-20000 psi/bar
60-510-15-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-15 psi/kPa
755-500-1-1-8-24-Orf	High Performance Digital Transmitter 500 PSIG
60-510-30-Psi	6" Pressure Gauge Liquid Filled 0 psi-30 psi
628-6000-1-1-H-14-3-Ch	628 Series IS Hammer Union Xmtr 6000psi, 0.25%FS, 4-20mA, Bendix

612-5-1-1-N-30	Submersible Level Transducer 0-5 PSI
60-510-2000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-2000 psi/bar
60-400-15000-Psi/Kpa	6" Pressure Gauge, 15000 PSI/kPa
615-750-1-2-6-14	
15 120 0 30vac	
60-410-3000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 3000 psi/kg/cm2
60-400-15000-Psi	6" Pressure Gauge, 15000 PSI
755-250-1-1-2-24	Digital Pressure Transducer 250 PSIG
5530-Mfs	5 Valve Manifold
60-500-2000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-2000 psi/bar
628-10000-1-1-H-14-44-Ch	628 Series IS Hammer Union Xmtr 10k psi, 0.25%FS, 4-20mA, Glenair
406-Mfs	3/4" NPT F Hard Seat SS Needle Valve
60-500-40000-Psi	6" Pressure Gauge Liquid Filled 0 psi-40000 psi
200-2000-2-2-2-1-St8	Pressure Transducer 0-2000 PSIG
60-500-15000-Psi	6" Pressure Gauge Liquid Filled 0 psi-15000 psi
100-30v-2-1-2-7	Pressure Transmitter -30"Hg-0
100-60a-2-1-2-2-0	Pressure Transmitter 0-60 PSIA
60-510-200-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-200 psi/kPa
60-500-5000-Psi	6" Pressure Gauge Liquid Filled 0 psi-5000 psi
628-5000-1-1-H-14-36-Ch	628 Series IS Hammer Union Xmtr 5000psi, 0.25%FS, 4-20mA, Cable
60-510-160-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-160 psi/kPa
615-30/300-1-1-2-1	Heavy Duty Pressure Transducer -30"Hg to300PSIG
60-500-5000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-5000 psi/bar
615-30/15-1-1-8-8	Heavy Duty Pressure Transducer -30"Hg to 15PSIG
800-1-2--14.5/145-2	RTD Temperature Transmitter
60-510-200-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-200 psi/kg/
60-410-1000-Psi/Bar	6"Press.Gauge, 1K PSI/bar, 1/2" 0 to 1000 psi/bar
45-1012-P25-S-2-P-1	4.5"Differential Pressure Gauge 0-25PSID
100-60-1-1-2-6-St8	Pressure Transmitter 0-60 PSIG 4-20mA Output, .5%FS, 1/4npt Male

100-30v-1-1-2-7	Pressure Transmitter -30 inHg to 0 psig
60-500-3000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 3000 psi/kg/cm2
60-500-30000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-30000 psi/kPa
615-30v-1-1-2-36	0PSIG
100-100-1-1-4-7-St8	Pressure Transmitter, 100PSIG 4mA-20mA 2-Wire, 1/8"NPTF, SS Orf
60-510-15-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-15 psi/kg/c
60-500-5000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-5000 psi/kPa
60-510-3000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-3000 psi/kg
60-410-30" Vac/Bar	6" Pressure Gauge -30 inHg/bar to 0
100-10-2-1-2-6	Pressure Transmitter, 10PSIG 4-20mA 2-Wire, 1/4"NPTM, 36"Cable
100-150-2-1-3-7	Pressure Transmitter, 150PSIG 4-20mA, Adj.SAE, Hirschmann Conn.
100-30/100-2-1-2-6	Pressure Transmitter -30 inHg to 100 psig
60-400-10000-Psi/Kpa	6" Pressure Gauge, 10000 PSI/kPa
615-10000-2-1-8-8	Heavy Duty Pressure Transducer 10000 PSIG
621-5000-1-1-2-6-St8	Explosion-Proof Pressure Transmitter 500 PSIG
621-300-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 300 PSIG
612-5-1-1-N-20	Submersible Level Transducer 5 PSIG
621-5000-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 5000 PSIG
615-200-2-2-6-14	
60-500-1000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 1000 psi/kg/cm2
200-500-2-2-2-3	Pressure Transducer, 500PSI
621-30-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 30 PSIG
615-300a-1-2-6-14	
60-500-15000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-15000 psi/kPa
100 150 2 1 2 25	
60-510-2000-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-2000 psi/kg
60-500-1500-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 1500 psi/kg/cm2
615-5000-1-2-6-14	

100-15a-1-1-2-1-St8 615-60a-1-2-6-14	Pressure Transmitter, 0-15 PSIA
615-30/15-1-1-2-8 615-15-2-2-6-14	Heavy Duty Pressure Transducer -30"Hg to 15 PSIG
60-500-20000-Psi 25-911-300psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi-20000 psi 2.5" Pressure Gauge 300 psi
60-500-1000-Psi 60-510-100-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi-1000 psi 6" Pressure Gauge Liquid Filled 0 psi/kPa-100 psi/kPa
615-15000-2-2-6-14 615-36000-1-2-6-14	
100-500-1-1-2-6 60-500-1500-Psi/Bar	Pressure Transmitter 0-500 PSI 6" Pressure Gauge Liquid Filled 0 psi/bar-1500 psi/bar
100-6000-1-1-2-6 621-10000-1-1-8-6-St8	Pressure Transmitter 6000 PSIG Explosion-Proof Pressure Transmitter 10000 PSIG
60-410-6000-Psi/Bar 615-15000-1-3-6-1-St8	6"Press.Gauge, 6K PSI/bar, 1/2" 0 to 6000 psi/bar Heavy Duty Pressure Transducer 15000 PSIG
628-6000-1-1-H-14-44-Ch 60-510-300-Psi	628 Series IS Hammer Union Xmtr 6k psi, 0.25%FS, 4-20mA, Glenair 6" Pressure Gauge Liquid Filled 0 psi-300 psi
412-Ffs 615-100a-2-2-6-14	1-1/2" NPTF Hard Seat SS Needle Valve
615-30000-1-1-6-8 621-3000-1-1-2-6	Heavy Duty Pressure Transducer 30000 PSIG Explosion-Proof Pressure Transmitter 3000 PSIG
45-1012-P5-S-2-P-1 615-150-2-2-6-14	4.5"Differential Pressure Gauge 0-5PSID
60-410-5000-Psi/Bar 60-410-1000-Psi/Kpa	6"Press.Gauge, 5K PSI/bar, 1/2" 0 to 5000 psi/bar 6" Pressure Gauge 0 to 1000 psi/kPa
408-Ffs 60-510-15000-Psi	1" NPTF Hard Seat SS Needle Valve 6" Pressure Gauge Liquid Filled 0 psi-15000 psi
60-410-6000-Psi/Kg/Cm2 615-150-1-1-2-8-St8	6" Pressure Gauge 0 to 6000 psi/kg/cm2 Heavy Duty Pressure Transducer 150 PSI

800-1-2-75-2	RTD Temperature Transmitter
200-2000-2-2-2-3	Pressure Transducer, 2000 PSI
621-200-1-1-8-6	Explosion-Proof Pressure Transmitter 200 PSIG
615-300-2-2-6-14	
60-500-10000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-10000 psi/bar
60-410-10000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 10000 psi/kg/cm2
60-510-5000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-5000 psi/bar
200-10000-2-5-3-7	Pressure Transmitter
60-500-15000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-15000 psi/bar
1000-3000-2-1-Rcp	Digital Pressure Gauge 0-3000PSIG
100-30/100-1-1-2-7	Pressure Transmitter -30"Hg 100PSIG
60-500-30000-Psi	6" Pressure Gauge Liquid Filled 0 psi-30000 psi
60-800-300	6" Test Gauge, 0-300psi
621-2000-1-1-8-6	Explosion-Proof Pressure Transmitter 2000 PSIG
60-500-5000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 5000 psi/kg/cm2
60-500-2000-Psi	6" Pressure Gauge Liquid Filled 0 psi-2000 psi
100-100-1-1-4-7	Pressure Transmitter, 100PSIG 4mA-20mA 2-Wire, 1/8"NPTF
60-500-30000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-30000 psi/bar
60-500-2000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 2000 psi/kg/cm2
628-6000-1-1-H-14-36-Ch	628 Series IS Hammer Union Xmtr 6000psi, 0.25%FS, 4-20mA, Cable
612-25-1-1-N-75	Submersible Level Transducer 0-25 PSIG
60-510-30" Vac/Kpa	6" Pressure Gauge Liquid Filled -30 inHg/kPa-0
615-4000-2-2-6-14	
60-400-20000-Psi/Kpa	6" Pressure Gauge, 20000 PSI/kPa
100-15-1-1-2-6	Pressure Transmitter, 0-15 PSIG
60-510-30-Psi/Kg/Cm2	6" Pressure Gauge Liquid Filled 0 psi/kg/cm2-30 psi/kg/c
615-30-1-1-2-8-St8	Heavy Duty Pressure Transducer 30 PSIG
615-30/15-1-1-8-1-St8	Transducer, -30 to 15psiG .25%FSA, 4-20mA, 1/2nptM, Orf
100-5000-1-1-2-6	Pressure Transmitter 5000 PSIG
60-500-1000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-1000 psi/bar

615-100000-1-2-6-14	
615-100-2-2-6-14	
615-58000-2-2-6-14	
621-3000-1-1-8-6-St8	Explosion-Proof Pressure Transmitter 3000 PSIG
410-Mfs	1-1/4" NPTF Hard Seat SS Needle Valve
615-6000-2-5-2-8	Heavy Duty Pressure Transducer 6000 PSIG
40-500-60000-Psi	4" Liquid Pressure Gauge 60000 psi
1000-5000-2-1-Rcp	Digital Pressure Gauge, 5K PSI 1/4"NPTM, Peak Memory, Protector
100-30vac-2-1-2-1	0 PSIG
621-200-1-1-2-6	Explosion-Proof Pressure Transmitter 200 PSI
615-1500-2-2-6-14	
60-410-2000-Psi	6" Pressure Gauge 2000 psi
60-510-200-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-200 psi/bar
60-500-10000-Psi/Kg/Cm2	6" Pressure Gauge Liquid 0 to 10000 psi/kg/cm2
625-5-2-1-2-8	Intrinsically Safe Pressure Transmitter 5 PSIG
60-500-60000-Psi	6" Pressure Gauge Liquid Filled 0 psi-60000 psi
621-10000-1-1-8-6	Explosion-Proof Pressure Transmitter 10000 PSI
60-510-6000-Psi	6" Pressure Gauge Liquid Filled 0 psi-6000 psi
628-20000-1-1-H-14-36-Ch	628 Series IS Hammer Union Xmtr 20k psi, 0.25%FS, 4-20mA, Cable
615-1000-2-2-6-14	
60-410-1000-Psi/Kg/Cm2	6" Pressure Gauge 0 to 1000 psi/kg/cm2
60-510-600-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-600 psi/bar
615-200a-1-2-6-14	
60-510-1000-Psi	6" Pressure Gauge Liquid Filled 0 psi-1000 psi
625-15000-1-1-8-14-St8	Pressure Transmitter, 15, 000psi .25%A, 4-20mA, 1/2 Conduit
615-115000-2-2-6-14	
200-200-2-5-2-7	Pressure Transducer 200 PSIG
200-3000-1-5-3-7-St8	Pressure Transducer, 3000PSI

625-2000-1-1-2-8 615-100a-1-2-6-14	Intrinsically Safe Pressure Transmitter 2000 PSIG
60-510-6000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-6000 psi/kPa
628-20000-1-1-H-14-44-Ch	628 Series IS Hammer Union Xmtr 20k psi, 0.25%FS, 4-20mA, Glenair
60-500-10000-Psi/Kpa	6" Pressure Gauge Liquid 10, 000psi/KPA
40-410-30000-Psi	4" Pressure Gauge 0 psi to 30000 psi
615-2-1-1-2-14	Heavy Duty Pressure Transducer 2 PSIG
615-10000-2-2-6-14	
200-500-2-2-2-7	Pressure Transducer 0-500 PSIG
60-510-1000-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-1000 psi/bar
628-20000-1-1-H-14-3-Ch	628 Series IS Hammer Union Xmtr 20k psi, 0.25%FS, 4-20mA, Bendix
60-500-1500-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-1500 psi/kPa
615-15-1-1-8-1	Heavy Duty Pressure Transducer 15 PSIG
60-510-160-Psi/Bar	6" Pressure Gauge Liquid Filled 0 psi/bar-160 psi/bar
625-30/30-2-1-8-36	Intrinsically Safe Pressure Transmitter -30" Hg to 30 PSIG
1000-145-2-1	Digital Pressure Gauge, 145PSI 1/4"NPTM, Peak Memory
60-510-30" Vac/Bar	6" Pressure Gauge Liquid Filled -30 inHg/bar-0
1000-10000-2-1-Rcp	Digital Pressure Gauge, 10K PSI 1/4"NPTM, Peak Memory, Protector
60-500-20000-Psi/Kpa	6" Pressure Gauge Liquid Filled 0 psi/kPa-20000 psi/kPa
60-800-2000psi	RTD Temperature Transmitter