



Fujikura

Garanti: 12 ay
Bu rne ait Trkiye ii kapı teslim fiyat ve teslim sresi ieren teklifimizi almak iin info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi iin +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz. **Fujikura** Markası, tedarik sresi iin ltfen bizimle iletiŐime geiniz.

Firmamız Fujikura Trkiye Distribtr veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen rnlerde sadece Orjinal ve yeni rn teklifi sunmaktadır. Bu sitede gsterilen zel marka adları ve ticari markalar ilgili sahiplerinin mlkiyetindedir, talep durumunda kaldırılmaktadır.

CM10-R10P-D(D7) FUJIKURA (DDK Electronics) | ElectroShield

rn	Aıklama
SP90S-PLUS	Fujikura splice station 90S + / CT50 1) Splicer 90S + 2) Internal battery (BTR-15) 3) AC adapter (ADC-20) and AC power cord (ACC-15) 4) Transport case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol container (AP-02), 3-hole stripping tool (SS03), Fiber holder holder (SP03) 7) Operating instructions 90S + (German) & brief operating instructions 8) CT50 fiberglass separator including fiber clamp & fiber residue container 9) Operating instructions CT50 (German) Detailed information: see data sheet consisting of each 90S-PLUS 90S + Fujikura splicer Lot number

	85158090 CT50 Fujikura fiber optic separator Lot number 84649000 German user manual 90S +, A6 paper format OPERATING INSTRUCTIONS 90S +
SP90S KOMFORTSET	The convenience set is used to optimize work processes and thus productivity. It includes brackets for a splice cassette and a splice protection press, as well as the Splice protection press as such. consisting of each Splice protection press for crimp splice protection Lot number 39269097 Splice protection press 1 pc Mounting bracket set for Fujikura 90S (+) Lot number 76169990 OPT-H90-
TOOL SET BASIC	Tool set for Fujikura splice station consisting of each Kevlar scissors with serrated edge and break notch Lot number 82130000 Kevlar scissors 1 pc Tube cutter, IDEAL, gray Lot number 82032000 LTC-02 1 pc Huby chopsticks made of cotton Lot number 56012190 BB-002 4 pack lint-free cleaning cloths for fibers, PU: 90 pcs Lot number 48189090 FW-01 1 PU Stripping tool from 250 or 200µm to 125µm Lot number 82032000 FO 103-S
Mass Fusion Splicer 41R Kit	https://www.fusionsplicer.fujikura.com/products/mass-fusion-splicer-41r-kit/
Mass Fusion Splicer 90R Kit	https://www.fusionsplicer.fujikura.com/products/mass-fusion-splicer-90r-kit-series-e/
FCX-MWL-F-AC-CH	PM - 16 2021 4711 FCX-MWL series FCX-MWL-F-AC-CH oxygen module Item description: 0.1...95% oxygen 0...950mVDC lin. Sensor with flow housing Old article designation before 04/01/2018: 103-12-102-0241
FH-100-900	FSM100 fiber holder for fibers with 890-1000µm coating
SP90S-PLUS	Fujikura splice box 90S+ / CT50 Scope of delivery: 1) Splicer 90S+ 2) Internal Battery (BTR-15) 3) AC Adapter (ADC-20) and AC Power Cord (ACC-15) 4) Transport case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol canister (AP-02), 3 hole stripping tool (SS03), Fiber holder mount (SP03) 7) Operating instructions 90S+ (German) & short operating instructions 8) CT50 fiber optic cleaver including fiber clip & fiber scrap container 9) Operating Instructions CT50 (German) consisting of each 90S+ Fujikura splicer Lot number 85158090 90S-PLUS 1 pc Fujikura fiber optic cleaver Commodity number 84649000 CT50 1 pc German operating instructions 90S+, A6 paper format INSTRUCTION MANUAL 90S+ 1 pc
SP90S COMFORT SET	Accessory set for splice space 90S(+) & CT50
TOOL SET BASIC	Tool set for Fujikura splice box
70S+	
SP41S-PLUS	Fujikura splice box 41S-PLUS / CT50 Description: Splice station with a particularly small, light, handy and fully automatic arc splicer 41S-PLUS for multimode and singlemode fibers, application in particular for the production of FTTH connections and work in the LAN and campus area. Fiber positioning via active V-groove alignment (in three axes) and control with 2 CCD cameras, 5.0 inch color screen, easy processing and insertion of the fibers using the fiber holder system. Memory for 10,000 splice results. NEW*: <input type="checkbox"/> Active Fusion Control technology <input type="checkbox"/> Active Blade Management Technology Scope of delivery: Splicer 41S-PLUS (2-year guarantee with annual maintenance), BTR-11 rechargeable battery, external power pack/charger ADC-19A, mains cable ACC-11, Clamp-S31A, 1 pair of spare electrodes ELCT2-16B (5000 splices), transport case CC - 36, fiber cleaver CT50 with fiber holder, 3 hole stripping tool (SS03), alcohol container (AP-02), fiber holder receiver (SP-01) Optional accessories: 1 pair each FH-70-250 fiber holder FH-70-900 fiber holder FH-FC-20 (900µm core in 2mm cable) FH-FC-30 (900µm core in 3mm cable) Clamp-S31B fiber clamp for 0.9mm loose tube cores FH-60-LT900 fiber holder for 0.9mm loose tube cores consisting of each Fujikura splicer 41S-PLUS Lot number 85158090 41S-PLUS 1 pc Fujikura fiber optic cleaver Commodity number 84649000

OPT-STATIV-ES	Tripod for 90S+/41S+ & NanoFlow MAX Professional tripod incl. extra wide quick-change adapter (incl. 1/4" & 3/8" screw) for a stable fixation. Thanks to the infinitely adjustable legs, working on uneven surfaces is no problem. Usable for Fujikura 90S/+, 41S/+, Fremco NanoFlow /MAX Tripod height: 160.5 cm / weight including adapter: 2 kg
TOOL SET BASIC	Tool set for Fujikura splice box Kevlar scissors 1 pc Loose tube cutter, IDEAL, grey Commodity number 82032000 LTC-02 1 pc Huby cotton chopsticks Commodity number 56012190 BB-002 4 Pack Lint-free cleaning cloths for fibers, PU: 90 pcs Lot number 48189090 FW-01 1 pack Stripping tool from 250 or 200µm to 125µm Commodity number 82032000
SP90S-PLUS	Fujikura splice box 90S+ / CT50 Scope of delivery: 1) Splicer 90S+ 2) Internal Battery (BTR-15) 3) AC Adapter (ADC-20) and AC Power Cord (ACC-15) 4) Transport case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol canister (AP-02), 3 hole stripping tool (SS03), Fiber holder mount (SP03) 7) Operating instructions 90S+ (German) & short operating instructions 8) CT50 fiber optic cleaver including fiber clip & fiber scrap container 9) Operating Instructions CT50 (German) consisting of each 90S-PLUS 1pc. 90S+ Fujikura splicer CT50 1 pc Fujikura fiber optic cleaver German operating instructions 90S+, A5 paper format INSTRUCTION MANUAL 90S+ 1 pc
CT08	Fujikura fiber optic cleaver with fiber plate Commodity number 84649000 Standard set cleave length 5 - 20m
Fiber optik pigtail (SC connector)	
FSM-40S A SM MM Fusion Splicer w/ Cleaver	
SP90S-PLUS	Splice space 90S+ / CT50 Scope of delivery: 1) Splicer 90S+ 2) Internal Battery (BTR-15) 3) AC Adapter (ADC-20) and AC Power Cord (ACC-15) 4) Transport Case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol canister (AP-02), 3 hole stripping tool (SS03), Fiber holder mount (SP03) 7) Operating instructions 90S+ (German) & short operating instructions 8) CT50 fiber optic cleaver including fiber clip & fiber scrap container 9) Operating Instructions CT50 (German) consisting of each 90S+ Fujikura splicer Lot number 85158090 90S-PLUS 1 pc Fujikura fiber optic cleaver Commodity number 84649000 CT50 1 pc German operating instructions 90S+, A5 paper format Commodity number 49011000 INSTRUCTION MANUAL 90S+ 1 pc
ELCT2-16B	90S(-PLUS)/41S/31S
XFPM-200KPG Pressure Sensor (Gauge Type), 4.5V,	
AFL-JP-06-TH	
FH-70-250	
FH-60-250	
FH-70-900	
FH-60-900	
AFL S014773	
XFPM-200KPG Pressure Sensor (Gauge Type), 4.5V,	
	Fujikura splicing station 100S / CT60 The new 100S splice station for multimode and single-mode fibers! Fiber positioning via active core centering (in three axes) and control with 2 CCD cameras, 4.95 inches movable color screen, easy stripping, processing and inserting of two fibers simultaneously with the revolutionary new fiber holder system.

SP100S	With splice times of up to 7 seconds and memory for 20,000 splice results. Intelligent features to optimize your work workflow: Simultaneous fiber preparation □ Active Fusion Control Technology □ Active Blade Management Technology CT60 Fujikura CT60 fiber optic cutting device INSTRUCTIONS FOR USE 100S German instruction manual, 100 pages, A5 paper format
SP90S-PLUS-	Fujikura splicing station 90S+ / CT50 Scope of delivery: 1) Splicer 90S+ 2) Internal battery (BTR-15) 3) AC adapter (ADC-20) and AC power cord (ACC-15) 4) Transport case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol container (AP-02), 3 hole stripping tool (SS03), fiber holder holder (SP03) 7) User manual 90S+ (German) & short user manual 8) Fiber optic separator CT50 including fiber clamp & fiber residue container 9) Operating instructions CT50 (German) Detailed information: see data sheet Warranty 90S+: 24 months Warranty CT50: 12 months consisting of 90S+ Fujikura splicer commodity number 85158090 90S-PLUS 1 pc Fujikura fiber optic cleaver commodity code 84649000 CT50 1 pc
FCX-MP-AC 0-5000	
SP100S KOMFORTSET	Accessory set for splicing station 100S & CT60 Expansion for press The comfort set is designed to optimize workflows and thus productivity. The set includes a holder system for the splice protection press as well as a splice protection press. consisting of each OPT-H100-11 Mounting bracket for Fujikura 100S splice protection press Splice protection press for crimp splice protection
BASIC TOOL SET	Tool set for Fujikura splicing station consisting of each Kevlar scissors with serrated edge and breaking notch Commodity code 82132000 Kevlar scissors, 1 pc. Hollow core cutter, IDEAL, gray Commodity code 82032000 LTC-02 1 pc Huby cotton sticks Product number 63079098 BB-002 4 Pack Lint-free cleaning cloths for fibers, pack size: 90 pieces Commodity code 48189090 FW-01 1 VE Stripping tool from 250 or 200µm to 125µm Product number 82032000 FO 103-S 1 pc
Annual Inspection Of L/Raft Type:Fm -Sv-15r,Cap:15person Serial No: Svr150883	
Annual Inspection Of L/Raft Type:Fm A-20h,Cap:20person Serial No: H205001	
Adc-13	
SP90S-PLUS// 90S+ / CT50	1) Splicer 90S+ 2) Internal Battery (BTR-15) 3) AC Adapter (ADC-20) and AC Power Cord (ACC-15) 4) Transport Case (CC-39) 5) Work table with tool drawers 6) 1 pair of spare electrodes (ELCT2-16B), alcohol canister (AP-02), 3 hole stripping tool (SS03), Fiber holder mount (SP03) 7) Operating instructions 90S+ (German) & short operating instructions 8) CT50 fiber optic cleaver including fiber clip & fiber scrap container 9) Operating Instructions CT50 (German)
70 S	
Fwd:- Sr. No. Svr60718 / Type: Fm-Sv-6rs / Capacity: 6 Person	
Acc-11 For Fsr-02	
70s/80s	
8522 Xfpm-050kpgpt	
50s Splice Tool Battery	
80s Maximum Complectation	
Cm10 – R10p – D (D7)	
Adc-09	

Adc-10 For Fsr-02
60s Kit
40s Fusion Splicer
1.5d-Qew
Adc-11
60s Or 70s Depend Of The Price
Stbd:- Sr. No. Svr251145 / Type: Frn-Sv-25rs / Capacity: 25 Person
70s/S015591
60 S Obsolete Replaced By 70s
Annual Inspection Of L/Raft Type:Frn -Sa-10h,Cap:10person Serial No: Sa100153
Fms-80s Fiber
62s Fusion Splicer
1.5d-Hqew
22s
Port:- Sr. No. Svr251146 / Type: Frn-Sv-25rs / Capacity: 25 Person
60s (Obsolete - Replaced By S015591) Splice Machine
Webasp2116m-1-D