



## Invicta

Garanti: 12 ay  
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in [info@yursat.com.tr](mailto:info@yursat.com.tr) e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz. **Invicta** Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

*Firmamız Invicta T¼rkiye Distrib¼t¼r¼ veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.*

¼r¼n	A¼ıklama
<a href="#">BLZ/60-105/6/01/50</a>	
<a href="#">283977</a>	NEW
<a href="#">6.2KW 960 D / D VIBRATION MOTOR</a>	
<a href="#">BLZ/50-75/6/01/50/JA</a>	VIBRATOR UNIT
<a href="#">BLZ 50-75/6</a>	4000 W \ 960 D/D \ 380 V \ 73575 N
<a href="#">BL/45-42/6/01/50</a>	
<a href="#">BL/50-75/6/01/50</a>	
<a href="#">BL/60-125/6</a>	
<a href="#">BLZ/40-35/4/01/50</a>	
<a href="#">BLZ/50-75/6</a>	
<a href="#">BLZ/75-185/6/01/50/A9</a>	
<a href="#">LM 695T</a>	
<a href="#">BLZ/60-105/6/1/50</a>	
<a href="#">BLZ/60-125/6/01/50</a>	VIBRATOR UNIT - 400V 50Hz
<a href="#">BLZ/40-35/4/01/50</a>	220/380V

<a href="#">BLZ/50-60/6/01/50</a>	VIBRATOR UNIT 220/380V
<a href="#">BL/40-35/6/01/50</a>	
<a href="#">BLZ/50-75/4/01/50</a>	VIBRATOR UNIT 230/400V
<a href="#">unbalance motor LM440T</a>	Spare part for serial number: 51I500150, Type UE 500x1250 FSD-2LM440T Weight 42 kg power output 0.5 kW speed 1440 rpm Rated current 1.32 A protection class IP66 operating voltage 400 V mains frequency 50 Hz Article No. 5T-51I500150001 Note: Please adjust the centrifugal weights as you did with the old unbalance motor! Painting: primed
<a href="#">unbalance motor LM445T</a>	Spare part for serial number: 51I500170, Type UE 650x1200 FHSD-2LM445T weight 45 kg power output 0.5 kW speed 1440 rpm Rated current 1.32 A protection class IP66 operating voltage 400 V mains frequency 50 Hz Article No. 5T-51I500170001 Note: Please adjust the centrifugal weights as you did with the old unbalance motor! Painting: primed
<a href="#">Blz / 50 / 75 / 6 / 01 Ja Identical With Blz/45-42/6/01/50/Ja Vibration Motor</a>	
<a href="#">04atex9054x Replaced By Blz/40-27/6/01/50 Motor</a>	
<a href="#">Blz/45-42/6/01/50/Ja Motor</a>	
<a href="#">Blz/40-27/6/01/50</a>	