

## Pomac

Garanti: 12 ay  
Bu rne ait Trkiye ii kapı teslim fiyat ve teslim sresi ieren teklifimizi almak iin [info@yursat.com.tr](mailto:info@yursat.com.tr) e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi iin +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.  
**Pomac** Markası, tedarik sresi iin ltfen bizimle iletiŐime geiniz.

*Firmamız Pomac Trkiye Distribtr veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen rnlerde sadece Orjinal ve yeni rn teklifi sunmaktadır. Bu sitede gsterilen zel marka adları ve ticari markalar ilgili sahiplerinin mlkiyetindedir, talep durumunda kaldırılmaktadır.*



rn	Aıklama
<a href="#">CK.GE.06LLM06X1</a>	RIGHT INSCHROEFKOP. CONICAL GE 6-LLM 6X1
<a href="#">CK.GE.06LLM08X1</a>	STRAIGHT REDUCTION SECRET. GE 6-LLM 8X1
<a href="#">CK.GE.06LLR02</a>	RIGHT INSERT HEAD, CONICAL GE 6-LLR02 1/8 "BSP
<a href="#">SN.H2.11-02</a>	H 2, R 1/8, 1/8 BSP, 11/6 71412 R 1/8 ' 11/6
<a href="#">SNB.ILC.03XR02</a>	HOLDING BAR 3 X 1/8
<a href="#">PLP 15-2</a>	
<a href="#">PLP-001</a>	Hygienic rotary lobe pump LEWA PLP 3-4   M   09L   06   M4V   E   E   P0   -   C1 Same pump head as previous delivery S/N 19.992 Medium mashed potatoes Viscosity 50'000-100'000 mPas Density 1.0kg/dm3 conveying capacity pump speed Volume/revolution 1.3 liters/revolution Differential pressure 5 bar Inflow condition Positive inflow Temperature 20°C (cleaning 85°C) heating no Pump housing 1.4404 (<=0.8 micron for all wet parts) Engine housing 1.4301 Shafts 1.4462 Duplex Rotors 1.4401 version BI-Wing C1 Connections pressure side DN 100 PN16 flange EN 1092-1 Type 11 without Counterpart (Ø114.3 x 3.6) Connections suction side

Rectangular inlet 88x170mm, left side of the Pump shaft seen Flow Horizontal; wave above Shaft seal Simple mechanical seal TC/TC EPDM according to FDA & EC1935/2004 Elastomeric EPDM according to FDA & EC1935/2004 Oil (pump) EP220 (0-30°C) food grade Rotors tolerance class compound clearance C1 Mounted pump with free shaft end Note Must be provided by the operator of the pump be sure that at any time product at the shaft seal pending.

[Code 7 1110.000.390](#)

[Code 6 8.0.1.00050](#)

[505.427](#)

[Code 33 0000.172.155](#)

[Piston Distributors For Pump Fkgm-Ep  
300:1](#)